



ਦਫਤਰ : ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਲੋ: ਨਿ: ਵਿ: (ਭਤੇਮ) ਸ਼ਾਖਾ ਗਿੱਦੜਬਾਹਾ

ਵੱਲ:-

ਪ੍ਰਿੰਸੀਪਲ,
ਅਕਾਲ ਅਕੈਡਮੀ
ਪਿੰਡ ਦੌਲਾ, ਤਹਿਸੀਲ ਗਿੱਦੜਬਾਹਾ
ਮੋਬਾਇਲ ਨੰਬਰ 988884- 81486, 98759-87321
aadaula@akalacademy.ac.in

ਨੰਬਰ:- 185

ਮਿਤੀ:- 23/07/2026

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ ਸਾਲ 2026-27 (Valid upto 31.03.2027)

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰ. AAD/Gen/06/2026 ਮਿਤੀ 19.06.2026 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਆਪ ਵੱਲੋਂ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ (ਸਾਲ 2026-27) ਦੀ ਮੰਗ ਕੀਤੀ ਗਈ। ਜਿਸ ਦੇ ਸਬੰਧ ਵਿੱਚ ਇਸ ਦਫਤਰ ਅਧੀਨ ਕੰਮ ਕਰਦੇ ਸਬੰਧਤ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ। ਸਕੂਲ ਵੱਲੋਂ ਦਿੱਤੇ ਪ੍ਰੋਫਾਰਮੇ ਅਨੁਸਾਰ ਦਰਸਾਇਆ ਪਲਿੰਥ ਏਰੀਆ 28752.22 ਵਰਗ ਫੁੱਟ ਅਤੇ ਬਿਲਡਿੰਗ ਸਟੋਰੀ Ground+2 ਹੈ। ਪੰਜਾਬ ਸਰਕਾਰ ਦੀ ਹਦਾਇਤਾਂ ਮੁਤਾਬਕ ਆਪ ਵੱਲੋਂ ਬਣਦੀ ਫੀਸ 10,000/- ਰੁਪਏ ਦਾ ਚਾਲਾਨ ਮਿਤੀ 16.07.2026 ਨੂੰ ਜਮ੍ਹਾਂ ਕਰਵਾ ਦਿੱਤਾ ਗਿਆ ਹੈ। ਪ੍ਰੋਫਾਰਮੇ ਦੇ ਕਾਲਮ ਨੰਬਰ 13 ਅਤੇ 14 ਸਬੰਧੀ ਦਫਤਰ ਫਾਇਰ ਸਟੇਸ਼ਨ, ਗਿੱਦੜਬਾਹਾ ਵੱਲੋਂ ਸਰਟੀਫਿਕੇਟ ਨੰਬਰ PBIP- (FIRE)/2026/ 7391 Dated 09.07.2026 ਰਾਹੀਂ ਜਾਰੀ ਕੀਤੇ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੇ ਆਧਾਰ ਤੇ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਮਿਤੀ 31.03.2027 ਤੱਕ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਵੇਗਾ:

1. ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀਆਂ ਛੱਤਾਂ ਉਪਰ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਖੜ੍ਹਾ ਨਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
2. ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀ ਕਿਸੇ ਜਗ੍ਹਾ ਤੇ ਤਰੇੜ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕਰਵਾ ਦਿੱਤਾ ਜਾਵੇ ਅਤੇ ਇਸ ਵਿਭਾਗ ਤੋਂ ਇੰਸਪੈਕਸ਼ਨ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ ਅਤੇ ਜਿਸ ਜਗ੍ਹਾ ਤੇ ਕਰੈਕ ਹੁੰਦੇ ਹਨ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਦੀ ਰਿਪੇਅਰ ਕਰਵਾਈ ਜਾਵੇ।
3. ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਪੱਖੋਂ ਸੇਫਟੀ ਦੀ ਸਾਰੀ ਜ਼ਿੰਮੇਵਾਰੀ ਸਕੂਲ ਮੁਖੀ ਦੀ ਹੋਵੇਗੀ। ਅੱਗ ਬਝਾਊ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿੱਚ ਹੋਣੇ ਚਾਹੀਦੇ ਹਨ, ਇਸ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਉਸਾਰੀ ਵਿੱਚ ਵਾਧਾ ਕਰਨਾ ਹੋਵੇ ਤਾਂ ਇਸਨੂੰ ਕੰਪੀਟੈਂਟ ਅਥਾਰਟੀ ਤੋਂ ਪਹਿਲਾਂ ਪਾਸ ਕਰਵਾਇਆ ਜਾਵੇ ਅਤੇ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਨਾ ਭੇਜੀ ਜਾਵੇ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਸਕੂਲ/ਸੰਸਥਾ ਮੁਖੀ ਨੂੰ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਜੇਕਰ ਇਹਨਾਂ ਸ਼ਰਤਾਂ ਵਿੱਚ ਕਿਸੇ ਸ਼ਰਤ ਦੀ ਉਲੰਘਣਾ ਕੀਤੀ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਕਤ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਤੁਰੰਤ ਪ੍ਰਭਾਵ ਤੋਂ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ ਅਤੇ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਬੰਧੀ ਇਸ ਵਿਭਾਗ ਦੀ ਕੋਈ ਜ਼ਿੰਮੇਵਾਰੀ ਨਹੀਂ ਹੋਵੇਗੀ।

ਇੱਥੇ ਇਹ ਵੀ ਸਪੱਸ਼ਟ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਪੱਤਰ/ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦਾ ਸਕੂਲ ਦੀ ਜਗ੍ਹਾ ਦੀ ਮਲਕੀਅਤ ਨਾਲ ਕੋਈ ਸਬੰਧ ਨਹੀਂ ਹੈ।

Manager

Principal
AKAL ACADEMY
Daula (Mkt.)

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਗਿੱਦੜਬਾਹਾ



ਦਫਤਰ : ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਲੋ: ਨਿ: ਵਿ: (ਭਤੇਮ) ਸ਼ਾਖਾ ਗਿੱਦੜਬਾਹਾ

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ:-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਗਿੱਦੜਬਾਹਾ ਜੀ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 392 ਮਿਤੀ 23.06.2026 ਅਤੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 376 ਮਿਤੀ 23.04.2026 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।
ਨੱਥੀ / ਸਕੂਲ ਕੋਸ 01 ਪੜ੍ਹਤ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਗਿੱਦੜਬਾਹਾ।

Manager
Akal Academy, Daula
(Sri Muktsar Sahib)

Principal
AKAL ACADEMY
Daula (Mkt.)
Aff. No. 1631284
School Code:- 21274

Translation punjabi into english

Seal Govt. of Punjab

Office: Sub Divisional Engineer, Provincial Sub Divisional P.H.W. (B&R)
Branch Gidderbaha

To,

Principal,
Akal Academy
Village Daula, Tehsil Gidderbaha.
Mobile No. 98884-81486, 98759-87321
aadaula @akalacademy.ac.in

No. :-185

Date: 23/07/2026



Subject :-

Reference: Regarding your letter no. AAD/Gen./06/2026 dated 19-06-2026.

Through the letter with the above subject and reference, you have demanded the Building Safety Certificate (Year 2026-27) of the school. In connection with which the building was inspected by the concerned Junior Engineer working under this office. As per the proforma given by the school, the plinth area shown is 28752.22 sq ft and the building story is Ground+2. As per the instructions of the Punjab Government, the fee due by you has been deposited in the challan of Rs. 10,000/- on 16.07.2026. Regarding columns 13 and 14 of the proforma, Office Fire Station, Gidderbaha, Hansen Mavtidivet Sanghath PBIP- (FIRE)/2026/7391 Dated 09.07.2026 On the basis of the School Building Safety Certificate dated 31.03.2027, the following conditions are issued:

1. Water should not be allowed to stagnate on and around the roofs of the school building.
2. If any crack appears in the building, that place should be vacated immediately and an inspection should be done immediately by this department and the place where the cracks occur should be repaired.
3. The entire responsibility for the safety of the building in every aspect will be with the school head. Fire extinguishers should be in working condition, if there is any need to increase the construction in this school building, it should be approved by the competent authority first and information should be sent to this office.

Translation Punjabi to English


Manager
Akmal Academy Daula


Principal
AKAL ACADEMY
Daula (Mkt.)
Aff. No. 1631

Apart from this, it is also written to the school/institution head that if any condition is violated in these conditions, then the said school building safety certificate will be considered cancelled with immediate effect and this department will not have any responsibility regarding building safety.

It is also clarified here that this letter/safety certificate has no connection with the ownership of the school premises.

Translation Punjabi to English

Sd/-
Sub Divisional Engineer,
Provincial Sub Divisional
B&R Branch. Gidderbaha

Endstt.No.:

Date:

A copy of the above is sent to the Executive Engineer, Construction Division, B.T.M. Branch, Gidderbaha for information and necessary action in respect of his Endstt. Number 392 dated 23.06.2026 and Endstt. Number 376 dated 23.04.2026.

Attached/ School Case 01 copy



Sd/-
Sub Divisional Engineer, .
Provincial Sub Divisional
B&R. Branch, Gidderbaha

ATTESTED

Angrej Singh Mann Advocate
Notary Public, Gidderbaha

10/9/26
Principal
AKAL ACADEMY
Daula (Mkt.)
Aff. No. 1631284
School Code:- 21274

Manager
Akai Academy, Daula
(Sri Muktsar Sahib)